



Arktos29 // Assembly Guide

STEP 1

Install (2153/ red seal) bearings + reducers (F) into upper and lower pivots. Use a coat of Green Loctite on upper bearings.

Be careful not to get reducers stuck behind bearings while installing.

Install bearings w/o reducers into swingarm (3903/ blue seal) + big link (2153/ red seal).

(See detailed/exploded views on pg. 5)

(Note: Use a liberal amount of preferred grease on any surface without Loctite for all assembly)

STEP 2

Install shock on big link. Fit is very tight. Once started, use the 5/32" punch to line up the shock and link holes.

STEP 3

Gently place shock into the upper mount & install the link using the mid thru-bolt (E).

(Only install part way as the DS spacer still needs to be installed)







STEP 4

Fully install the mid thru-bolt (E), making sure to place the spacer (D) between the frame and link on the DS (seating thru-bolt will require some force). Then install the DS collet bolt (C), followed by the NDS collet bolt (B). Torque both to 22nm.

Install both shock mounting bolts (0 & P) using 4mm & 6mm allen wrenches; torque to 7nm.


STEP 5

Install the "Baby" Link Axle (I) and "Baby" Links (L) with the "Baby" Link Bolts (K). Torque to 25nm.

Install the upper pivot thru-bolt (A) with an 8mm allen wrench, attaching the swingarm to the big link. Only thread in a few threads, fully tighetning will make the next step more difficult.

STEP 6

Install the main pivot bolts (J) using a 10mm allen wrench. Torque to 25nm.





STEP 7


Fully install the upper thru-bolt (A) until snug, then install the collet bolts. Torque to 22nm.

STEP 8

Install the caps (N) to the lower pivot with the cap bolts (M) using a 4mm allen wrench. Torque to 7nm.

STEP 9

You're all set to go. Build 'er up and get shreddy!





INDEX



A- Upper Thru Bolt

B- NDS Upper Collet Bolt

C- DS Upper Collet Bolt

D- Mid Link/Frame Spacer

E- Mid Thru Bolt

F- Bearing Reducer(s)

G-DS Mid Bolt

H- NDS Mid Collet Bolt

I- Low/ "Baby" Link Axle

J- Main Pivot Bolts

K- "Baby" Link Bolts

L- "Baby" Links

M- Cap Bolts


N- Caps

O- Small Shock Bolts


P- Large Shock Bolts

Q-Big Link

EXPLODED VIEWS














EXPLODED VIEWS













BEARING INSTALL

Big Link







Lower Pivot

Swingarm





